



INCIDENT

Incident Number **2023-00015852** Incident Date **10/29/2023** NFIRS Number **0015969** Incident Type **(111) - Building fire**

FDID **61091** Station **Station 62** Shift **B Shift** District **62E**

Initial Dispatch Code
FIRE STRUCTURE

Alarms Working Fire? **Yes** COVID-19 was a factor **No, COVID-19 was not a factor** Critical Incident Critical Incident Team

Temporary Resident Involvement
None

Hazardous Materials Released

Action Taken 1
(10) - Fire control or extinguishment, other

Action Taken 2
(12) - Salvage & overhaul

AID

Aid Given/Received
(1) - Mutual aid received

Aided Agency Their Incident Number

Aiding Agencies
Flagler Beach Fire Department, Palm Coast Fire Department, Bunnell Police Department, Ormond Beach Fire Department, Florida State Fire Marshal, Flagler County Sheriff

LOCATION

Location Type
(1) - Street address

Address
301 East MOODY Boulevard, Bunnell, Florida, 32110

Cross Street, USNG, or Directions Latitude **29.46683674** Longitude **-81.25629064** Census Tract

Detector Alerted Occupant

Property Use **(181) - Live performance theater** Mixed Use

 **TIMES**

PSAP Received <u>22:03:07, 10/29/2023</u>	Dispatch Notified Time <u>22:03:30, 10/29/2023</u>	Alarm Time <u>22:03:30, 10/29/2023</u>
Arrival Time <u>22:06:14, 10/29/2023</u>	Water on Fire Time <u>22:15:00, 10/29/2023</u>	At Patient Time <u></u>
Loss Stop Time <u>05:30:00, 10/29/2023</u>	Controlled Time <u>06:00:00, 10/30/2023</u>	Last Unit Cleared Time <u>14:33:01, 10/30/2023</u>
Total On Scene Time <u>16 hrs 26 mins 47 sec</u>	Total Incident Time <u>16 hrs 29 mins 54 sec</u>	

 **COUNTS**

Counts Include Aid Received?

Yes**Suppression:**

Apparatus Personnel

8 22**EMS:**

Apparatus Personnel

3 6**Other:**

Apparatus Personnel

6 7
 **LOSS**
Property:

Estimated Property Losses

100000000Estimated Property Value
Content:

Estimated Content Losses

300000Estimated Content Value
 **AUTHORIZATION**
Report Writer:

Name

SMITH, JERRY

Employee Number

S0680Assignment
Authorization Date
Officer in Charge:


Name

BARRY, BRADY

Employee Number

B0842Assignment

Authorization Date

11/01/2023**Quality Control:**Name
Authorization Date
 **INCIDENT NARRATIVE**

Fire units were dispatched to a smoke coming from the roof of the former Baptise church now Flagler playhouse. upon arrival battalion 62 found the structure with heavy smoke coming from the roof's eve and ridge vents found during a 360 survey. Command was established at this time and E62 was directed to the front of the building to Starte a search of the structure with R62. upon entre the crews were met with heavy smoke conditions and advanced into the structure discovering fire in the back upper story of the structure and where able to conduct a fire attack on the fire. after a few minutes it became evident that the crews where not making any headway on the fire and the order was given to evacuate the building. all crew where able to exit safely and a defensive attack was started. it was noted that the fire had progressed through the roof of the building and was venting at this time. T24 was placed on the A side of the building, L11 was placed on the B side and Q93 from Ormond placed on the D side to establish an aerial master stream.

Created By: BARRY, BRADY


Unit Reports
RES62

Use	Responding From	Priority
(2) - EMS		Emergent

Response Delays

None/No Delay

Dispatch Time	Enroute Time	Arrival Time
22:03:37, 10/29/2023	22:05:36, 10/29/2023	22:06:41, 10/29/2023
At Patient Time	Clear Time	In District Time
	04:36:27, 10/30/2023	

Actions Taken:

Search, Extinguishment by fire service personnel

Personnel Count

0**Unit Narrative**

R62 arrived on scene as the first arriving rescue, and we were assigned to primary search of the "Flagler Playhouse" building. A full search was performed, and there were no notable findings during search. The search was extended to the fire building, where we searched behind the stage, up the stairs, and found the fire room. The information was relayed over the radio, and we hastily met with the attack crew at the front of the building to guide them on where to go to reach the fire. Fire was found and suppressed with attack line. R62 headed to rehab. R62 proceeded to help E62 with search of a non-involved nearby building; all clear and no notable findings. R62 then proceeded to be general manpower throughout the remainder of our time at the call. R62 was then relieved by command to rehab and return to service.

Created By: BRANDS, ADRIAN

TEN92

Use	Responding From	Priority
(1) - Suppression		Emergent

Response Delays

Other (Not Listed)

Dispatch Time	Enroute Time	Arrival Time
22:03:37, 10/29/2023	22:08:40, 10/29/2023	22:15:19, 10/29/2023
At Patient Time	Clear Time	In District Time
	04:49:31, 10/30/2023	

Actions Taken:

Fire control or extinguishment, other, Provide water

Personnel

JAKE GONZALEZ, NOAH HUNT

Unit Narrative

Prior to arrival Tender 92 was directed to park on the Bravo side of the building. Heavy smoke and fire noted on the BC corner. Tender 92 linked up with Engine 25 crew. We made our way to the BC corner of the building with flames showing through a 2nd floor window in the attic area. Orders were given to crews to soften the building. Crews forced approximately 4-5 doors. Engine 16 was requested to reposition to our location. Engine 16 was originally positioned on the C side of the structure. Engine 16 relocated to the B side and parked in the grass. Tender 92 supplied Engine 16 with water. Tender 92 crew assisted in deployment and placement of 400' of 1 3/4" line and placement of the master stream. Line was charged and entry was made on the Bravo side. Fire quickly traveled across the attic space and was seen through the ridge vent and gable end vents. Command was informed of findings by Tender 92 LT and Engine 16 LT. Command communicated with interior crew and asked their progress at which point they were ordered out of the building. Tender 92 LT requested Engine 16 driver initiate evacuation air horn blast. Engine 16 driver did so. Water supply to a hydrant was established by Tender 92 and Engine 16 drivers. Once out of the building all members were separated based on their unit and a PAR check was conducted - all found to be PAR. We transitioned to a defensive operation. Tender 92 LT was assigned Charlie Division by command. Charlie Division. B side and C side exposure were cooled down constantly and conditions reassessed. Ground monitor and deck gun was also utilized for fire suppression. Command was informed of findings / changes in conditions. Tender 92 crew along with FF from Rescue 92 assisted in checking for extension / overhaul on the Delta side. Tender 92 crew after overhaul assisted in repacking of LDH and handlines as the fire was going to be handled with aerial units. Tender 92 was released by command and returned to station for showers and post-fire decontamination of equipment.

Created By: GONZALEZ, JAKE

BAT62

Use (0) - Other	Responding From	Priority Emergent
---------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

Dispatch Time 22:03:36, 10/29/2023	Enroute Time 22:06:31, 10/29/2023	Arrival Time 22:06:31, 10/29/2023
--	---	---

At Patient Time	Clear Time 07:26:16, 10/30/2023	In District Time
-----------------	---	------------------

Actions Taken:
Incident command

Personnel
BRADY BARRY

Unit Narrative

Fire units were dispatched to a smoke coming from the roof of the former Baptise church now Flagler playhouse. upon arrival battalion 62 found the structure with heavy smoke coming from the roof's eve and ridge vents found during a 360 survey. Command was established at this time and E62 was directed to the front of the building to Starte a search of the structure with R62. upon entre the crews were met with heavy smoke conditions and advanced into the structure discovering fire in the back upper story of the structure and where able to conduct a fire attack on the fire. after a few minutes it became evident that the crews where not making any headway on the fire and the order was given to evacuate the building. all crew where able to exit safely and a defensive attack was started. it was noted that the fire had progressed through the roof of the building and was venting at this time. T24 was placed on the A side of the building, L11 was placed on the B side and Q93 from Ormond placed on the D side to establish an aerial master stream.

Created By: BARRY, BRADY

ENG62

Use (1) - Suppression	Responding From	Priority Emergent
---------------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

ENG62

Dispatch Time 22:03:36, 10/29/2023	Enroute Time 22:04:33, 10/29/2023	Arrival Time 22:06:14, 10/29/2023
At Patient Time	Clear Time 07:25:00, 10/30/2023	In District Time

Actions Taken:

Extinguishment by fire service personnel, Search, Salvage & overhaul

Personnel

ARMANDO CASTANEDA, JAMES MELADY, ANDRE TICHONOFF

Unit Narrative

E62 dispatched to a report of a structure fire. Arrived on scene and positioned by command at the alpha side of the structure. E62 crew reported having visible smoke from the eaves on the alpha, bravo, and delta side. E62 assigned R62 crew to force the doors and search the annex directly to the east of the main building. E62 forced the main doors and performed a rapid primary search. Smoke conditions on the interior were moderate to heavy with limited visibility past the vestibule. An inspection hole just inside the front door was made with a hook and heavy volume driven smoke was noted. E62 It reported to command the fire may be on the charlie side and met up with R62, R52, and PCFD L25. The crews split and assisted with advancing the charged 1 3/4 to the charlie side where what appeared to be the seat of the fire was located and extinguished. E62 It noted at this time to command that interior conditions had changed lightly after the application of water, but the smoke from the inspection hole appeared to be getting worse, leading the E62 crew to consider a fire in the void spaces closer to the Charlie/delta corner. After fire vented through the roof, command reassigned all units to the bravo side. E62 crew was assigned to take R62 and clear the two story annex to the south. After cleared, E62It was designated as Alpha division supervisor. E62 crew assisted by providing manpower salvage and overhaul, and active firefighting duties. E62 It monitored conditions on the alpha side and reported frequently directly to IC. Once the fire was deemed out, E62 crew assisted with salvage and overhaul and loading equipment. E62 crew released from the scene without incident.

Created By: CASTANEDA, ARMANDO

RESS1

Use (2) - EMS	Responding From	Priority Emergent
-------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

Dispatch Time 22:06:10, 10/29/2023	Enroute Time 22:06:10, 10/29/2023	Arrival Time 22:10:22, 10/29/2023
At Patient Time	Clear Time 04:54:10, 10/30/2023	In District Time

Actions Taken:

Fire control or extinguishment, other

Personnel

JOHN KRALL, ZACHARY SCHROEDER

Unit Narrative

R51 self dispatches to the call based on hearing the call come out and knowing the location. R51 arrives on scene and is advised to bring man power to the A side of the structure. R51 crew meets E62 crew who advises they and rescue 62 are performing a search. R51 crew is met with smoke about 6ft off the ground just inside the structure. R51 places an inspection hole in the ceiling just inside the front door to check conditions. Light smoke is noted to come out of the hole. Upon entering the main entrance of the play house no visible fire is seen and even with the thermal imaging camera nothing obvious is noted. R51 crew is met by R62 crew who advise that they found the fire in the back of the structure behind the stage. R51 crew and R62 crew grab the 1 3/4 line and advance it though the seating area the what is believed to be over the stage and into the back stage area. A back up line is called to be deployed. At this time a small amount of fire is noted at the base of stairs. with more fire noted up the stairwell. Crew extinguishes first fire and advances up the stairs. At the top of the stairs there is moderate fire noted. Water is put on fire however as soon as that is done visibility drops. from that point forward a tic was used to find areas of heat. The bulk of the fire was never fully located. It appeared to be in void spaces on the second floor that we were not able to get good access to. Outside crews advise that fire had vented through the roof in our location however the hose team was never able to locate that fire. Command makes decision to pull interior crews out of the structure and go defensive. R51 crew then assists E16 and T92 with water supply and defensive operations for the rest of the event.

Created By: KRALL, JOHN

ENG16

Use	Responding From	Priority
(1) - Suppression		Emergent

Response Delays

None/No Delay

Dispatch Time	Enroute Time	Arrival Time
22:09:31, 10/29/2023	22:09:31, 10/29/2023	22:20:44, 10/29/2023
At Patient Time	Clear Time	In District Time
	05:02:31, 10/30/2023	

Actions Taken:

Extinguishment by fire service personnel, Provide manpower, Provide apparatus

Person 1: FROLING, KARL

Fire Products Exposed To

Smoke, Heat, Fire, Debris/Runoff, Gases/CO

PPE Worn During Incident

Boots, Work Gloves, Coat, Firefighting Gloves, Structure Firefighting Helmet, Hood, Mask, SCBA, Pant

PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth
No	No	No	No

Decontamination Procedures Completed

Used wet wipes

Person 2: NAJPAVER, KYLE

Fire Products Exposed To

Gases/CO, Fire, Heat, Smoke, Debris/Runoff

PPE Worn During Incident

SCBA, Boots, Firefighting Gloves, Coat, Pant, Structure Firefighting Helmet, Mask, Hood, Work Gloves

PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth
No	No	No	No

Person 2: NAJPAVER, KYLE

Decontamination Procedures Completed

Used wet wipes

Person 3: SABATINO, MATTHEW

Fire Products Exposed To

Debris/Runoff, Smoke, Fire, Heat, Gases/CO

PPE Worn During Incident

Work Gloves, Boots, Mask, Hood, Pant, Firefighting Gloves, Structure Firefighting Helmet, Coat, SCBA

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Used wet wipes

Person 4: Gall, Cassidy

Fire Products Exposed To

Smoke, Heat, Fire, Gases/CO, Debris/Runoff

PPE Worn During Incident

Coat, Structure Firefighting Helmet, Pant, Work Gloves, Boots, Mask, Hood, Firefighting Gloves, SCBA

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Used wet wipes

Unit Narrative

E-16 dispatched to this location for a structure fire. Upon arrival responded to the bravo side of the structure and attack line pulled from E-16 to assist interior attack crew. Crews evacuated structure and E-16 established a ground monitor and deck gun operations on the B/C corner. E-16 crew then assigned to D-side and E-16 LT assumed D-division with Q-93 for exposure control on D-side. E-16 and E-25 crew made entry to delta side for fire attack on D-side and unable to get total access to fire in attic due to interior set-up. D-side door and rear garage door forced during operations. E-16 remained on D-side until released by command.

Created By: FROLING, KARL

CHF101

Use (0) - Other	Responding From	Priority Emergent
---------------------------	-----------------	-----------------------------

Response Delays

None/No Delay

Dispatch Time

22:14:40, 10/29/2023

Enroute Time

22:15:17, 10/29/2023

Arrival Time

22:21:11, 10/29/2023

At Patient Time

Clear Time

06:14:28, 10/30/2023

In District Time

Actions Taken:

Provide information to public or media

Personnel

MICHAEL TUCKER

Unit Narrative

Arrived on-scene and received assignment from IC to serve as "Safety". Additionally at closeout of the incident involved PIO activities.

Created By: TUCKER, MICHAEL

FM92

Use (0) - Other	Responding From	Priority Non-Emergent
---------------------------	-----------------	---------------------------------

Response Delays
None/No Delay

Dispatch Time 22:21:47, 10/29/2023	Enroute Time 22:27:38, 10/29/2023	Arrival Time 22:27:41, 10/29/2023
--	---	---

At Patient Time	Clear Time 14:33:01, 10/30/2023	In District Time
-----------------	---	------------------

Actions Taken:

Investigate, Provide information to public or media, Notify other agencies., Provide manpower

Personnel

JERRY SMITH, JUSTIN MCDONALD

Unit Narrative

See Investigation Tab.

Created By: SMITH, JERRY

RES24

Use (2) - EMS	Responding From	Priority Emergent
-------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

Dispatch Time 22:38:07, 10/29/2023	Enroute Time 22:40:03, 10/29/2023	Arrival Time 22:57:42, 10/29/2023
--	---	---

At Patient Time	Clear Time 03:58:24, 10/30/2023	In District Time
-----------------	---	------------------

Actions Taken:

Provide manpower, Provide advanced life support (ALS), Standby

Personnel

EVELYN HENRIQSON, REUBEN ZUAZUA

Unit Narrative

R24 dispatched to a structure fire. R24 set up as Rehab along with the Air trailer. No incident was reported.

Created By: ZUAZUA, REUBEN

ATT31

Use (1) - Suppression	Responding From	Priority Non-Emergent
---------------------------------	-----------------	---------------------------------

Response Delays
None/No Delay

Dispatch Time 00:06:53, 10/30/2023	Enroute Time 00:06:53, 10/30/2023	Arrival Time 00:06:53, 10/30/2023
--	---	---

At Patient Time	Clear Time 03:37:33, 10/30/2023	In District Time
-----------------	---	------------------

Actions Taken:
Fill-in or moveup

Personnel Count
0

Unit Narrative

Logistical support. Drinking water and air trailer for SCBA refills.

Created By: SMITH, JERRY

 **Fire Module**

 **SITE INFO**

Alarms	Acres Burned	Resident Units In Bldg Not residential	Buildings Involved
Hydrant Identifier	Estimated Water Usage		

 **IGNITION**

Area of Origin
(75) - Wall assembly, concealed wall space

Heat Source
(UU) - Undetermined

Item First Ignited (UU) - Undetermined	Fire Confined to Item?
--	------------------------

Type of Material First Ignited

Cause of Ignition
(U) - Cause undetermined after investigation

Factors Contributing to Ignition 1
(UU) - Undetermined

Human Factors Contributing to Ignition
(N) - None

Est. Age of Person Involved	Gender of Person Involved
-----------------------------	---------------------------

EQUIPMENT

Equipment Involved in Ignition
(NNN) - None

Equipment Power Source

Equipment Portability

Brand

Model

Serial Number

Year

Fire Suppression Factor 1
(161) - Attic undivided

MOBILE PROPERTY

Mobile Property Involved
(N) - None

Type

Make

Model

Year

License Plate Number

State

VIN

Car Stolen?

STRUCTURE

Structure Type

(1) - Enclosed building

Stories Above Grade

2

Stories Below Grade

0

Building Status

(2) - In normal use

Length

79 ft

Width

125 ft

Total Square Feet

9875 sq ft

Story of Fire Origin

2

Fire Spread

(4) - Confined to building of origin

Item Contributing Most to Flame Spread

(17) - Structural member or framing

Type of Material

(63) - Sawn wood, including all finished lumber

Number of Stories with Damage

Minor Damage

Significant Damage

Heavy Damage

Extreme Damage

Total Stories

PROTECTIVE SYSTEMS

Presence of Detector

(1) - Present

Detector Type

(5) - More than one type present

Power Supply

(4) - Hardwire with battery backup

Detector Operations

(3) - Detector failed to operate

Effectiveness (/Failure Reason)

Presence of Auto Extinguishing System

(N) - None Present

System Type

PROTECTIVE SYSTEMS

System Operation

of Sprinklers

Reason for System Failure

Investigation

AGENCY REFERRED TO

Agency

Florida State Fire Marshal

Phone Number

(386) 323-0941

Case Number

23-3537

ORI

FID

FDID

Address

500 Fentress Boulevard, G, Daytona Beach, Florida, 32114

CASE INFO

Case Status

(1) - Investigation open

Avail. of Material First Ignited

(2) - Available at scene

Property Ownership

(1) - Private

Lead Agency Investigator

SMITH, JERRY

Other Agency Investigators

JUSTIN MCDONALD

Laboratories Used

(N) - None

Initial Observations

(5) - Fire department forced entry

Other Investigative Info

SCENE SECURITY

Scene Security

Secured

Secured By

Flagler County Fire Rescue/Bunnell Police Department

Scene Turned Over To

Fire Department Forced Entry?

Yes

Open Prior or After FD Arrival?

WEATHER

Weather Type

(10) - Clear, less than 1/10 cloud cover

Wind Direction

(N) - None/calm

Wind Speed

Special Weather Conditions

INVESTIGATION INFO

Entry Method

(UU) - Unknown

Extent of Fire Involvement on Arrival

(4) - Fire through roof

Incendiary Device Container

(NN) - No container

Incendiary Device Ignition Delay

(NN) - No device

Incendiary Device Fuel

(NN) - None

INVESTIGATION INFO

Suspected Motivation 1

(UU) - Unknown

Group Involvement 1

(U) - Unknown

INVESTIGATION REMARKS

Responded out to structure fire per request from on duty Battalion Chief Barry. Upon arrival found structure well involved in fire. Fire coming from the roof of the structure. I could not enter the structure until 0800 am do to firefighting activities. I did work the out side of the structure. working counter clockwise starting on the Alpha side of the structure. Finding very heavy damage at the eaves of the roof. Moving counter clockwise to the Bravo side of the structure finding the same thing. Heavy fire damage in the roof and eve area. Working my way to the Charlie side of the structure I find myself working around two more building two story in height with no fire involvement light smoke do to all the buildings being connected. Fire was contain to the attic space of the main building. Building is of type III ordinary construction. Fire ran through the attic until the roof collapsed into the building.

I made entry from the Alpha side of the structure. Work from less damage to most damage. Finding most damage to be in the attic that had collapsed inside the building. Working up the stairs behind the stage to the second floor. Still the damage is above the ceiling. Most of the trusses that have not falling in are consist with an attic fire charring on the top of the trusses clean on the bottom side of the trusses. Coming back down the stairs we notice part of the drywall missing from the wall in the stairwell beside a chimney. Inside this wall we find heavy charring and some missing wall studs. While looking and this area and the depth of charring and the missing wall studs, and the lack of fire damage below this area, and the amount of fire damage coming up and out of this area. companied with the direct line to the attic space with no fire stops. we found this to be the area of origin. For the cause of it will be undetermined do to fire damage itself.

Detective Darryl King

Department of Financial Services

Division of Investigation & Forensic service

Bureau of Fire, Arson and Explosives Investigations

Office Number 386-323-0904

Case# 2023-3537

On 11/1/23 at 0900 met with Fire investigator Douglas Rowell of ProNet Group representing the Insurance company. Mr. Rowell was provided response details of FCFR to the incident along with initial size up and tactics with the aid of FCFR E62 B-shift Lt. Castaneda. Facilitated Mr. Rowell with obtaining video camera footage from the Flagler County Historical Societies exterior camera.

Douglas Rowell

Fire Investigator

ProNet Group inc

(732) 859-8759

drowell@pronetgroup.com

In addition to assisting Mr. Rowell. Conducted a post incident walk through with BC Barry, BC Van Deusen, DC Aspinwall, E-62 B- Shift R-62 B-Shift. Followed up with Mr. Rowell in the afternoon to see if FCFR could offer any further assistance at this time. Mr. Rowell did not require any further assistance at this time.

Owner

Flagler Play House Inc.

Jerri Berry

386-569-9708