
# **Boating Fatalities**

#### **Boating Fatalities photo detail**


Photos Courtesy of FWC

The 19-foot motorboat was launched on Lake Harney in Seminole County. While the vessel was operating on the water, it made a course change and collided with a tree at the shoreline. The 20-year-old operator was fatally injured during the collision and received blunt force trauma to his body. Investigators could not determine a cause for the sudden change in direction.



<sup>2020</sup> FATALITIES - TOP TEN STATES


#### FLORIDA TOTAL FATALITIES RECORDED




 ${\rm *Fatality} \; {\rm Rate-Number} \; {\rm of} \; {\rm fatalities} \; {\rm per} \; 100,000 \; {\rm registered} \; {\rm vessels}$ 

INVESTIGATING AGENCY

<sup>\*2021</sup> statistics for top 10 states were not available at time of printing Source: U.S. Coast Guard Boating Safety Division (recreational fatalities)




Fatality data includes six missing persons where their disappearance is associated with a boating accident



#### ACCIDENT TYPES


\*59 fatal accidents involving 60 fatalities (Based on first harmful event)


**OPERATION AT TIME OF ACCIDENT** 




#### \*68 vessels involved in 59 fatal accidents with 60 victims









#### VESSEL PROPULSION, LENGTH & TYPE





A PWC was traveling north in the St. Joseph Sound, outside of the marked channel close to channel marker 16. A 27-foot motorboat was traveling east in the same area but within the marked channel. The PWC was traveling at a high rate of speed with a weaving course toward the motorboat. The motorboat operator saw the PWC and believed he was going to cut through the channel behind him. The operator redirected his attention to his port side to navigate heavy boat traffic traveling in the opposite direction. The PWC attempted a quick evasive movement to the port side in attempt to avoid the motorboat unsuccessfully and struck the motorboat midship. The PWC operator was ejected, impacting the motorboat and falling into the water. He was transported to the hospital where he later died.




20

Boating Accident Statistical Report

# **2021 BOATING FATALITIES**


#### VICTIM RESIDENCY



\*59 accidents involving 60 fatalities

(Alcohol/drug related refers to any accidents in which alcohol or drug use may have been a contributing factor, whether legally impaired or not)

#### PRIMARY CAUSE OF ACCIDENT BY REVIEWING AUTHORITY



\*Offshore defined as the edge of the Gulf Stream or three miles from shore, whichever is greater, in the Atlantic and more than nine miles from shore in the Gulf of Mexico.